# UNSAFE STRUCTURES BOARD CITY COMMISSION MEETING ROOM - CITY HALL JUNE 17, 2004 3:00 P.M.

## HEARING COMPUTER SCHEDULED

\_\_\_\_\_\_

CASE NO: CE03121109 CASE ADDR: 1115 NW 3 AV

OWNER: MORGAN, GENE & CINDY EDWARDS VICE

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 111.1.1

THE C.B.S. REAR STRUCTURE AND WOODEN STORAGE SHED HAVE DETERIORATED FROM THE ELEMENTS AND HAVE NOT BEEN MAINTAINED ACCORDING TO THE REQUIREMENTS OF THE FLORIDA BUILDING CODE OR THE MINIMUM HOUSING CODE OF THE CITY OF FORT LAUDERDALE.

FBC 111.2.1.1.1

THE BUILDING IS VACANT AT THIS TIME.

FBC 111.2.1.2.1

THE FASCIA, SOFFIT AND CEILING IS FALLING DUE TO EXPOSURE TO THE ELEMENTS.

FBC 111.2.1.2.2

THE ROOF, ROOF STRUCTURE, CEILING, THE DOORS AND WINDOWS, ARE ALL PARTIALLY DESTROYED DUE TO THE EXPOSURE TO THE ELEMENTS AND NOT BEING MAINTAINED PROPERLY.

FBC 111.2.1.2.4

THERE ARE SETTLEMENT CRACKS AROUND THE CONCRETE BLOCK STRUCTURE.

FBC 111.2.1.2.5

THE ELECTRICAL IS PARTIALLY DESTROYED DUE TO THE EXPOSURE TO THE ELEMENTS.

FBC 111.2.1.2.6

THERE ARE SEVERAL PILES OF DOG FECES ON THE FLOOR AND THE WASTE SYSTEM IS NOT WORKING, CAUSING AN UNSANITARY CONDITION.

FBC 111.2.2.1

THE COST TO ALTER OR REPAIR THE BUILDING EXCEEDS 50% OF THE VALUE OF THE BUILDING.

FBC 111.2.2.2

THE COST OF THE STRUCTURAL REPAIRS EXCEEDS 33% OF THE VALUE OF THE BUILDING.

## UNSAFE STRUCTURES BOARD

#### CITY COMMISSION MEETING ROOM - CITY HALL

JUNE 17, 2004

3:00 P.M.

\_\_\_\_\_\_

CASE NO: CE04031526 CASE ADDR: 801 NW 19 AVE

OWNER: BLACK DIAMOND PROPERTIES, SAMANTHA JOHNSON, AS REGISTERED AGENT

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 111.1.1

THE C.B.S. DUPLEX HAS DETERIORATED FROM THE ELEMENTS AND HAS NOT BEEN MAINTAINED ACCORDING TO THE REQUIREMENTS OF THE FLORIDA BUILDING CODE OR THE MINIMUM HOUSING CODE OF THE CITY OF FORT LAUDERDALE.

FBC 111.1.2

THE INTERIOR RENOVATION APPLICATION A99021978 HAS FAILED PLAN REVIEW, ON 3/11/99 AND HAS NOT BEEN PICKED UP FOR CHANGES, THUS IT IS NULL AND VOID.

FBC 111.2.1.1.1

THE BUILDING IS BOARDED AT THIS TIME AND HAS BEEN SINCE 1999.

FBC 111.2.1.2.2

THERE ARE SEVERAL LEAKS IN THE ROOFS, SEVERAL OF THE CEILING 3 X 6 BEAMS ARE ROTTED OR TERMITE DAMAGED, THE DOORS AND SEVERAL OF THE INTERIOR PARTITIONS ARE ROTTED OR TERMITE DAMAGED.

FBC 111.2.1.2.3

THE ROOF IS PARTIALLY DESTROYED DUE TO THE EXPOSURE TO THE ELEMENTS.

FBC 111.2.1.2.4

THE FASCIA, SOFFIT AND ROOF TAILS ARE ROTTED DUE TO EXPOSURE TO THE ELEMENTS OR TERMITE DAMAGE AND SOME OF IT IS HANGING.

FBC 111.2.1.2.5

THE ELECTRICAL IS PARTIALLY DAMAGED DUE TO THE VANDALS.

FBC 111.2.1.2.6

THE PLUMBING IS PARTIALLY DESTROYED DUE TO VANDALS.

FBC 111.2.2.1

THE COST TO ALTER OR REPAIR THE BUILDING EXCEEDS 50% OF THE VALUE OF THE BUILDING.

FBC 111.2.2.2

THE COST OF THE STRUCTURAL REPAIRS EXCEEDS 33% OF THE VALUE OF THE BUILDING.

FBC 111.2.2.4

# UNSAFE STRUCTURES BOARD CITY COMMISSION MEETING ROOM - CITY HALL JUNE 17, 2004 3:00 P.M.

CE03051368 CASE NO: CASE ADDR: 1225 NW 16 ST

OWNER: FLETCHER-ALLEN, SHIRLEY M & VERNON C. HILLS & DELBERT HILLS

& JAMES HILL

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 111.1.1

THE RESIDENTIAL SINGLE STORY CONCRETE MASONRY STRUCTURE HAS DETERIORATED FROM THE ELEMENTS AND HAS NOT BEEN MAINTAINED ACCORDING TO THE REQUIREMENTS OF THE FLORIDA BUILDING CODE OR THE MINIMUM HOUSING CODE OF THE CITY OF FORT LAUDERDALE.

FBC 111.2.1.2.2

THE STRUCTURE IS UNIFORMLY DESTROYED DUE TO TERMITE AND WATER DAMAGE. SOME OF THE STRUCTURAL ROOF TRUSSES AND JOISTS ARE DETERIORATED AND ROTTED.

FBC 111.2.1.2.3

THE ROOF SHEATHING HAS DETERIORATED AND IS MISSING IN AREAS.

FBC 111.2.2.1

THE COST TO ALTER OR REPAIR THE BUILDING EXCEEDS 50% OF THE VALUE OF THE BUILDING.

FBC 111.2.2.2

THE COST OF THE STRUCTURAL REPAIRS EXCEEDS 33% OF THE VALUE OF THE BUILDING.

\_\_\_\_\_\_

CASE NO: CE03102473 CASE ADDR: 2531 NW 16 ST WATKINS, DOROTHY A INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 111.1.1

THE RESIDENTIAL SINGLE STORY CONCRETE MASONRY STRUCTURE HAS DETERIORATED FROM THE ELEMENTS, AND HAS NOT BEEN MAINTAINED ACCORDING TO THE REQUIREMENTS OF THE FLORIDA BUILDING CODE OR THE MINIMUM HOUSING CODE OF THE CITY OF FORT LAUDERDALE.

# UNSAFE STRUCTURES BOARD CITY COMMISSION MEETING ROOM - CITY HALL JUNE 17, 2004 3:00 P.M.

#### FBC 111.2.1.1.1

THE STRUCTURE IS VACANT, UNGUARDED AND OPEN AT DOORS AND WINDOWS.

# FBC 111.2.1.1.2

THE IS AN UNWARRANTED ACCUMULATION OF DUST, DEBRIS OR OTHER COMBUSTIBLE MATERIALS THEREIN.

## FBC 111.2.1.1.3

THE BUILDING CONDITION CREATES HAZARDS WITH RESPECT TO MEANS OF EGRESS AND FIRE PROTECTION AS PROVIDED HEREIN FOR THE PARTICULAR OCCUPANCY.

### FBC 111.2.1.2.1

THERE IS A FAILURE, HANGING LOOSE OR LOOSENING OF ANY SIDING BLOCK, BRICK, OR OTHER BUILDING MATERIAL.

# FBC 111.2.1.2.2

THERE IS A DETERIORATION OF THE STRUCTURE OR STRUCTURAL PARTS.

## FBC 111.2.1.2.3

THE INTERIOR OF THE BUILDING IS PARTIALLY DESTROYED.

# FBC 111.2.1.2.5

THE ELECTRICAL OR MECHANICAL INSTALLATIONS OR SYSTEMS CREATE A HAZARDOUS CONDITION IN VIOLATION OF THE STANDARDS OF THIS CODE.

# FBC 111.2.1.2.6

AN UNSANITARY CONDITION EXISTS BY REASON OF INADEQUATE OR MALFUNCTIONING SANITARY FACILITIES OR WASTE DISPOSAL SYSTEMS

## FBC 111.2.2.1

THE COST TO ALTERATION, REPAIR OR REPLACEMENT OF THE UNSAFE STRUCTURE EXCEEDS 50% OF THE VALUE OF THE STRUCTURE.